

World Housing Encyclopedia

A Resource on Construction in Earthquake Regions



an initiative of
Earthquake Engineering Research Institute (EERI) and
International Association for Earthquake Engineering (IAEE)

HOUSING REPORT

RC Structural Wall Building : Moment frame with in-situ shear walls

Report#	78
Last Updated	
Country	Romania
Author(s)	Maria D. Bostenaru, Ilie Sandu,
Reviewers	Vanja Alendar,

Important

This encyclopedia contains information contributed by various earthquake engineering professionals around the world. All opinions, findings, conclusions & recommendations expressed herein are those of the various participants, and do not necessarily reflect the views of the Earthquake Engineering Research Institute, the International Association for Earthquake Engineering, the Engineering Information Foundation, John

General Information

Building Type:	RC Structural Wall Building : Moment frame with in-situ shear walls
Country:	Romania
Author(s):	Maria D. Bostenaru Ilie Sandu
Last Updated:	
Regions Where Found:	<p>Buildings of this construction type can be found in all parts of Romania, and is particularly common in the capital Bucharest. This construction can be found in six quarters (districts) of Bucharest: Militari, Colentina, Drumul Taberii, Pantelimon, Berceni, Iancului, with the total of 8,000 apartment units. Except Iancului, other quarters are located in the suburban area of the city and consist mainly of newer settlements (built after the World War II). Concrete shearwall construction is commonly used for the urban residential construction and it accounts for over 60% of the new buildings. There are four different types of shear wall construction which were affected by the 1977 earthquake - type "OD" described in this contribution is one of them. This type of housing construction is commonly found in urban areas.</p>

This is typical urban multi-family housing practiced throughout Romania in the period from 1965 to 1989. There are many existing buildings of this type at the present time, with about 8,000 apartments in Bucharest alone. Concrete shear wall construction is commonly used for the residential construction and it accounts for over 60% of new housing. Buildings of this type are typically 10 or 11 stories high. The main load-bearing structure is a cast in-situ concrete shear wall structure supported by RC solid slabs. Each building block consists of several (5-6) identical building units ("tronsons" in Romanian) separated by means of seismic joints. The walls are continuous throughout the building height and orientated in two directions, with only one centrally located wall in the longitudinal direction and eight walls in the transverse direction. In addition, there are some lightweight concrete partition walls. This building plan is known as the honeycomb

Summary:

("fagure") plan. The buildings are often supported by mat foundations due to soft (alluvial) soil conditions. Many buildings of this type were designed according to the 1963 Romanian Building Code (P13-1963) which was updated in 1970 (P13-1970). The 1963 Code considered a magnitude 7 design earthquake for the Bucharest area. This region is well known as a seismically prone area, with the epicentre of damaging earthquakes close to Vrancea. Earthquakes with the Richter magnitude of over 7.0 occur once in 30 years. Bucharest, the capital, is located around 150 km south of the epicentre and lies in the main direction of the propagation of seismic waves. The Bucharest area is located on the banks of the Dmbovita and Colentina river, on non-homogeneous alluvial soil deposits. During the earthquake of 4 March 1977 (Richter magnitude 7.2), over 30 buildings collapsed in Bucharest, killing 1,424 people. The buildings of "OD" type suffered damages of various extent in the 1977 earthquake, and one building unit ("trason") totally collapsed (that was the only shear wall building that collapsed in t

Length of time practiced:	25-60 years
Still Practiced:	No
In practice as of:	1989
Building Occupancy:	Residential, 20-49 units
Typical number of stories:	10-11
Terrain-Flat:	Typically
Terrain-Sloped:	Off
Comments:	Currently, this type of construction is not being built. This construction was practiced in the period from 1965 to 1989.


Features

Plan Shape	Rectangular, solid
Additional comments on plan shape	Buildings of this type are of rectangular shape, with a very large length/width aspect ratio (of over 10).
Typical plan length (meters)	137.5
Typical plan width	11.5


(meters)	11.5
Typical story height (meters)	2.6
Type of Structural System	Structural Concrete: Structural Wall: Moment frame with in-situ shear walls
Additional comments on structural system	<p>This building type is characterized with a so-called "honeycomb" ("fagure" in Romanian) building plan characteristic for the Romanian housing design. It consists of box-type units creating rooms. Due to such building configuration, the walls are well connected and are able to carry the loads in a uniform manner. The walls are supported by 120 mm reinforced concrete solid slabs clamped in the walls and elastically supported by the facade beams. These buildings are typically supported by mat foundations. The lateral load-resisting system is reinforced concrete structural walls (with frame). The main lateral load-resisting structure consists of reinforced concrete shear walls supported by RC slabs. The walls are continuous throughout the building height and laid in two directions, with only one centrally located wall in the longitudinal direction and eight walls in the transverse direction (four are continuous over the building width, and other four are of smaller length). The transverse shear walls end on facade with "bulbs"- boundary elements. Wall thickness is on the order of 140 mm. Walls are rather lightly reinforced, with one layer of 12 mm diameter vertical bars and 8 mm horizontal bars. The reinforcement spacing varies from 150 mm (longitudinal direction) to 250 mm (transverse direction) on centre. There are light concrete partition walls.</p>
Gravity load-bearing & lateral load-resisting systems	
Typical wall densities in direction 1	2-3%
Typical wall densities in direction 2	4-5%
Additional comments on typical wall densities	The typical structural wall density is up to 5%. (1.4% - 4.8%) 1.4% in the longitudinal direction and 4.8% in the transverse direction.
Wall Openings	One window and door opening per room, in some cases with a door leading to balcony/loggia. The total window area is about 25% of the overall wall area, and the total door area is even smaller. The

walls with windows are generally not load-bearing structures.

Is it typical for buildings of this type to have common walls with adjacent buildings?	No
Modifications of buildings	No modifications were observed.
Type of Foundation	Shallow Foundation: Mat foundation
Additional comments on foundation	The Bucharest area is located on non-homogeneous alluvial soil deposits. The buildings usually rest on mat foundations.
Type of Floor System	Other floor system
Additional comments on floor system	Structural concrete: solid slabs (cast-in-place, precast)
Type of Roof System	Roof system, other
Additional comments on roof system	Structural concrete: solid slabs (cast-in-place, precast)
Additional comments section 2	<p>When separated from adjacent buildings, the typical distance from a neighboring building is 0.07 meters. Typical Plan Dimensions: Length of a building unit (tronson) = 27.5 m; length of entire building (with 5 tronsons) = 137.5 m Typical Span: Spans are variable in the range from 2.2 m to 4.6 m (based on the available information). Each building consists of several (5-6) identical building units (tronsons in Romanian) of rectangular shape separated by means of seismic joints. "OD" in Romanian stands for Double Orientation ("Orientare Dubla") - meaning that the larger apartments have light from two sides (i.e. in the morning and in the afternoon) in different rooms. This building type is characterized with a so-called "honeycomb" ("fagure" in Romanian) building plan typical for the Romanian housing design. It consists of smaller box-type units creating rooms. In this system, there are no corridors, and the rooms are connected only by means of openings (doors and windows). This construction is characterized with large cantilevered balconies.</p>



Key Load-Bearing Elements- a typical building unit (tronso)



Key Load-Bearing Elements- a typical building unit (tronso)



Building Materials and Construction Process

Description of Building Materials

Structural Element	Building Material (s)	Comment (s)
Wall/Frame	ReinforcedConcrete	Characteristic Strength- Concrete:cube compressive strength 25 MPa Reinforcement: tensilestrength 370 or 520 MPa
Foundations	ReinforcedConcrete	Characteristic Strength- Concrete:cube compressive strength 25 MPa Reinforcement: tensilestrength 370 or 520 MPa
Floors	ReinforcedConcrete	Characteristic Strength- Concrete:cube compressive strength 25 MPa Reinforcement: tensilestrength 370 or 520 MPa
Roof	ReinforcedConcrete	Characteristic Strength- Concrete:cube compressive strength 25 MPa Reinforcement: tensilestrength 370 or 520 MPa :
Other		

Design Process

Who is involved with the design process?	EngineerArchitect
Roles of those involved in the design process	Designprofessionals (engineers and architects) were involved in the design and construction of this type.
Expertise of those involved in the design process	The quality of design and construction was ensured by "The State Inspection for Construction".

Construction Process

Who typically builds this construction type?	Other
Roles of those involved in the building process	These buildings were built as residential construction by the government-owned companies.
Expertise of those involved in building process	The quality of design and construction was ensured by "The State Inspection for Construction".
Construction process and phasing	Between 1960-1990 all construction was performed by government-owned companies. Technical professionals wereinvolved in the construction. The construction of this type of housing takes place in a single phase. Typically, thebuilding is originally designed for its final constructed size.
Construction issues	

Building Codes and Standards

Is this construction type address by codes/standards?	Yes
Applicable codes or standards	P13-1970, STAS 8000-67.The year thefirst code/standard addressing this type of construction issued was 1963. The code refers explicitly to seismic designof buildings (issued in 1963 and revised in 1970) P13-1963, P13-1970; the latest Code is P100-1992. The most recentcode/standard addressing this construction type issued was 1996. Title of the code or standard: P13-1970, STAS8000-67 Many buildings of this type were designed according to the P.13-1963 Romanian Code, although the Code waschanged in 1970 (P13-1970). The P13-1963 Code considered a magnitude 7 earthquake for the Bucharest area.

Process for building code enforcement

Building Permits and Development Control Rules

Are building permits required?

Yes

Is this typically informal construction?

No

Is this construction typically authorized as per development control rules?

Yes

Additional comments on building permits and development control rules

Building Maintenance and Condition

Typical problems associated with this type of construction

Who typically maintains buildings of this type?

Owner(s)Renter(s)

Additional comments on maintenance and building condition

Construction Economics


Unit construction cost

At the time of the original construction (1974) the unit cost was 1170 lei/m².


Labor requirements

The information is not available as the construction company ceased to exist in 1990.


Additional comments section 3




Plan of a Typical Building



Plan of a Typical Building Unit (tronson)



Key Seismic Features - Shear Wall Layout (note only one shear wall in the longitudinal direction)



Key Seismic Deficiencies - Significantly Smaller Wall Density in the Longitudinal Direction

Socio-Economic Issues

<p>Patterns of occupancy</p>	<p>One family per housing unit (apartment). Each building typically has 21-50 housing unit(s).</p>
<p>Number of inhabitants in a typical building of this construction type during the day</p>	<p>Other</p>
<p>Number of inhabitants in a typical building of this construction type during the evening/night</p>	<p>Other</p>
<p>Additional comments on number of inhabitants</p>	<p>About 120 people inhabit each building unit ("tronson"); there are typically 5 tronsons per</p>

NUMBER OF INHABITANTS	building.
Economic level of inhabitants	Middle-income class
Additional comments on economic level of inhabitants	House Price/Annual Income (Ratio)1:1 or better
Typical Source of Financing	Owner financedGovernment-owned housing
Additional comments on financing	
Type of Ownership	Own outright
Additional comments on ownership	
Is earthquake insurance for this construction type typically available?	Yes
What does earthquake insurance typically cover/cost	There is "The Voluntary Complex Insurance of the Households and Physical Persons"through ASIROM.
Are premium discounts or higher coverages available for seismically strengthened buildings or new buildings built to incorporate seismically resistant features?	No
Additional comments on premium discounts	
Additional comments section 4	

Earthquakes

Past Earthquakes in the country which affected buildings of this type

Year	Earthquake Epicenter
1977	Vrancea
1986	Vrancea
1990	Vrancea

Past Earthquakes

Damage patterns observed in past earthquakes for this construction type

This region is well known as a seismically prone area, with the epicenter of damaging earthquakes close to Vrancea. Earthquakes with the Richter magnitude of over 7.0 occur once in 30 years. Bucharest, the capital, is located around 150km south of the epicenter and lies in the main direction of the propagation of seismic waves. The Bucharest area is located on the banks of the Dmbovita and Colentina river, on non-homogeneous alluvial soil deposits. During the earthquake of 4 March 1977 (Richter magnitude 7.2), over 30 buildings collapsed in Bucharest, killing 1,424 people. It should be noted that the buildings of "OD" type suffered damages of various extent in the 1977 earthquake, and one building unit ("trason") totally collapsed (that was the only shear wall building that collapsed in the earthquake). Buildings with their longitudinal direction aligned parallel with the direction of seismic waves (mainly in Berceni and Drumul Taberii areas of Bucharest) were most affected. The damage patterns were the strongest on the OD16 site. The earthquake action in 1977 was mainly in NNE-SSV direction. Out of 167 building units ("trasons") of the "OD" type existing in Bucharest at the time of the 1977 earthquake, only 7 were lightly damaged; the remaining building units suffered a partial collapse (7 units) or were damaged (19 significantly damaged, 72 moderately damaged, 61 lightly damaged) Balan (1982), Argent (1998). According to the reports, damages to this construction type were due to inadequate wall density in the longitudinal direction, inadequate amount and detailing of wall reinforcement, lack of lateral confinement in the walls and in the boundary elements ("bulbs") causing brittle concrete failure and buckling of reinforcement. In addition, quality of concrete construction was found to be rather poor. No damages to the buildings of this type were observed in the 1986 and 1990 earthquakes. In the 1977 earthquake (M 7.2), no significant damages were observed on other buildings of similar construction.

Shear Walls - Damage was more pronounced in the

Additional comments on earthquake damage patterns

longitudinal wall(vertical and inclined cracks); - Cracking in the transverse walls was more pronounced at the lower levels where extensive "X" cracks developed in the piers between the door openings); - Brittle failure of wall end zones with spalling and bursting of the concrete at the base and buckling of reinforcement bars; - see Figures 15 and 16 "Bulbs" - Brittle failure with concrete spalling and crushing at the base and buckling of the reinforcement (OD16 building) - Crushing of concrete and reinforcement buckling at the first floor level (OD1 example) - see Figure 17 Lintels- Extensive cracking

Structural and Architectural Features for Seismic Resistance

The main reference publication used in developing the statements used in this table is FEMA 310 "Handbook for the Seismic Evaluation of Buildings-A Pre-standard", Federal Emergency Management Agency, Washington, D.C., 1998.

The total width of door and window openings in a wall is: For brick masonry construction in cement mortar : less than 1/2 of the distance between the adjacent cross walls; For adobe masonry, stone masonry and brick masonry in mud mortar: less than 1/3 of the distance between the adjacent cross walls; For precast concrete wall structures: less than 3/4 of the length of a perimeter wall.

Structural/Architectural Feature	Statement	Seismic Resistance
Lateral load path	The structure contains a complete load path for seismic force effects from any horizontal direction that serves to transfer inertial forces from the building to the foundation.	TRUE
Building Configuration-Vertical	The building is regular with regards to the elevation. (Specify in 5.4.1)	TRUE
Building Configuration-Horizontal	The building is regular with regards to the plan. (Specify in 5.4.2)	TRUE
Roof Construction	The roof diaphragm is considered to be rigid and it is expected that the roof structure will maintain its integrity, i.e. shape and form, during an earthquake of intensity expected in this	TRUE

area.

Floor Construction	The floor diaphragm(s) are considered to be rigid and it is expected that the floor structure(s) will maintain its integrity during an earthquake of intensity expected in this area.	TRUE
Foundation Performance	There is no evidence of excessive foundation movement (e.g. settlement) that would affect the integrity or performance of the structure in an earthquake.	TRUE
Wall and Frame Structures-Redundancy	The number of lines of walls or frames in each principal direction is greater than or equal to 2.	FALSE
Wall Proportions	Height-to-thickness ratio of the shear walls at each floor level is: Less than 25 (concrete walls); Less than 30 (reinforced masonry walls); Less than 13 (unreinforced masonry walls);	TRUE
Foundation-Wall Connection	Vertical load-bearing elements (columns, walls) are attached to the foundations; concrete columns and walls are doveled into the foundation.	TRUE
Wall-Roof Connections	Exterior walls are anchored for out-of-plane seismic effects at each diaphragm level with metal anchors or straps.	N/A
Wall Openings		TRUE
Quality of Building Materials	Quality of building materials is considered to be adequate per the	FALSE

requirements of national codes and standards (an estimate).

Quality of Workmanship	Quality of workmanship (based on visual inspection of a few typical buildings) is considered to be good (per local construction standards).	FALSE
Maintenance	Buildings of this type are generally well maintained and there are no visible signs of deterioration of building elements (concrete, steel, timber).	N/A

Building Irregularities

Additional comments on structural and architectural features for seismic resistance	
Vertical irregularities typically found in this construction type	Other
Horizontal irregularities typically found in this construction type	Other
Seismic deficiency in walls	- Inadequate (too small) wall thickness of 140mm; - Inadequate wall density in the longitudinal direction (one shear wall only); - Significantly different wall density in the two principal directions (i.e. larger wall density in the transverse direction)
Earthquake-resilient features in walls	- Large stiffness, resulting in small displacements and minimized damage to nonstructural elements;
Seismic deficiency in frames	
Earthquake-resilient features in frame	
Seismic deficiency in roof and floors	
Earthquake resilient	

features in roof and floors

Seismic deficiency in foundation

Earthquake-resilient features in foundation

Seismic Vulnerability Rating

For information about how seismic vulnerability ratings were selected see the [Seismic Vulnerability Guidelines](#)


	High vulnerability		Medium vulnerability		Low vulnerability	
	A	B	C	D	E	F
Seismic vulnerability class				-	o	-




Collapse of OD16 Building in the 1977 Vrancea Earthquake




Building Collapse in the 1977 Vrancea Earthquake (OD16 Building)



Typical Earthquake Damage in RC Shear Walls (1977 Vrancea Earthquake)



Typical Earthquake Damage in RC Shear walls; note cracking in the construction joint(1977 Vrancea Earthquake)



Typical Earthquake Damage to a Boundary Element (bulb) (1977 Vrancea Earthquake)

Retrofit Information

Description of Seismic Strengthening Provisions

Structural Deficiency	Seismic Strengthening
Shear walls: inadequate wall thickness and reinforcement	- Cast in-situ RC jacketing of the boundary elements-bulbs (see Figure 18). A special care is taken to ensure the adequate bond between the new and existing concrete. - Jacketing with glass fibre woven fabric and epoxy resins in the severely damaged areas
Cracks in shear walls and lintels	Small cracks - injecting the cracks with epoxy grout; Large cracks - filling the cracks with epoxy mortar (paste)
Small cracks in shear walls and lintels	Crack injections with epoxy resins. This was the most widely used method to repair the damages after the 1977 earthquake. The domestic resin DINOX 10L was used per the INCERC technology (C. 183-77). The injection is applied by cleaning the surface, making the injection holes and applying the resin.
Additional comments on seismic strengthening provisions	<p>The above described methods are used for seismic retrofit of RC structures in Romania. These methods were used for retrofitting the buildings OD16 and OD1 damaged in the 1977 earthquake.</p> <p>Seismic strengthening was performed in the design practice after the 1977 earthquake. Many buildings in Bucharest were damaged in the 1977 earthquake, however the strengthening was not performed in most cases. For that reason, in 1999-2000 the Ministry for Public Works (MLPA) established a special committee to evaluate seismic resistance and possible retrofit requirements for this construction type according to the P100-1992 Code (latest edition issued in 1996). The scale of work and financial resources required for the retrofit are quite significant. As a result, the progress is rather slow and in case of an earthquake a significant life and property loss could be expected.</p>
Has seismic strengthening described in the above table been performed?	
Was the work done as a mitigation effort on an undamaged building or as	The work was done as a repair following earthquake damage

1977NBSU.S. Department of Commerce/National Bureau of Standards, NBS Special Publication 490, Washington, DC, USA 1977

Expertizarea si punerea Agent,R.Fast Print, Bucharest, Romania 1998

Authors

Name	Title	Affiliation	Location	Email
Maria D. Bostenaru	Researcher	Urban and Landscape Design Department, Ion Mincu University of Architecture and Urbanism	str. Academiei nr. 18-20, Bucharest 010014, ROMANIA	maria.bostenarudan@alumni.uni-karlsruhe.de
Ilie Sandu			Sos. Oltenitei 34 Bl. 5C et. V ap. 23, Bucharest 7000, ROMANIA	

Reviewers

Name	Title	Affiliation	Location	Email
Vanja Alendar	Research Associate	Dept. of Civil Engineering, University of Belgrade	Belgrade 11001, SERBIA	vanja@imk.grf.bg.ac.yu